

WELD 1010 : Oxyfuel and Plasma Cutting

Introduces fundamental principles, safety practices, equipment, and techniques necessary for metal heating and oxyfuel cutting, and Plasma cutting. Topics include: metal heating and cutting techniques, metal heating and cutting techniques, manual and automatic oxyfuel cutting techniques, and oxyfuel pipe cutting, plasma torch and theory, plasma machine set up and operation and plasma cutting techniques.

Credits 4

Corequisites

WELD 1000